

Arborist Report

YR-2022/1106

Tree Risk Assessment (TRA)

134 Hereford Road, Mt Evelyn

Original report prepared by: (Grad Cert Arboriculture, ISA Tree Risk Assessment Qualified)

Report Date: 28 September 2022

Amendment prepared by: (Adv Cert Arboriculture, ISA Tree Risk Assessment Qualified)

Amended Report Date: 14 December 2022

Contents

1. Summary of Assessment.....	1
2. Tree Plan	2
3. Tree Assessment Table	3
Appendix 1 Tree Risk Assessment Forms.....	

1. Summary of Assessment

- 1.1 The original scope of this report was to inspect trees in the road reserve (the site) and assess tree risk relative to the use of 134 Hereford Road, Mt Evelyn. During the course of the assessment, the site was attended on four occasions between 1/9/2022 – 27/9/2022. Trees have been tagged with identification numbers (numbered 1 to 25). **However, this amended report is only for eight trees recommended for removal by Council at the 22 November Council meeting.** Trees were assessed with the aid of a soil probe, diameter measuring tape, GIS software, camera phone and the ISA Tree Risk Assessment Form.
- 1.2 The site slopes down approximately 10 degrees to the south and is partially exposed to the prevailing south-westerly winds as well as easterly winds. The site is protected from northerly winds by a ridge line and tall trees on private property.
- 1.3 The house at 134 Hereford Road, Mt Evelyn, which is adjacent to the site, is nestled amongst a stand of mature eucalypt. Over time numerous trees in the road reserve bordering this property have been subjected to excavation, level changes, pavement and/or compaction within root zones.
- 1.4 At the time of the assessment parts of the site were very wet and subject to overland stormwater flows. In particular, the soils directly north of 134 Hereford Road and the table drain along the west side of Kookaburra Lane were saturated.
- 1.5 In the past 18 months a tree fell from the edge of the table drain on Kookaburra Lane and impacted the house at 134 Hereford Road, Mt Evelyn. Numerous other trees around the site and on adjoining private property have also fallen – many as a result of a severe storm event that impacted the Yarra Ranges in June 2021.
- 1.6 This amended report considers eight trees in the road reserve that were recommended for retention in the original report but approved for removal by Council at the 22 November Council meeting. Risk assessments were undertaken by Nicholas Magree (Arborist) to determine risk ratings and suggest risk mitigation options for each tree (see appendix 1). Risk mitigation options were reviewed by the Coordinator of Trees (Paul Mechelen) and subsequent actions have been recommended (see section 3).

2. Tree Plan

Road Reserve North of 134 Hereford Road, Mt Evelyn Planning Application Site Plan (proposed trees circled in red and tagged onsite)



3 Tree Assessment Table

Tree No.	Botanic Name	Tree within 10m of dwelling?	Vitality	DBH (cm)	Height (m)	Spread dia. (m)	Overall Risk	Recommended Action
3	<i>Eucalyptus obliqua</i>	No	Normal	80	25	16	Low	No action
4	<i>Eucalyptus obliqua</i>	No	Normal	70	30	9	Low	No action
8	<i>Eucalyptus obliqua</i>	No	Normal	66	30	14	Low	No action
16	<i>Eucalyptus obliqua</i>	Yes	Normal	84	30	10	Low	Clean crown of dead wood and undertake aerial inspection of the crown
17	<i>Eucalyptus obliqua</i>	Yes	Low	70	25	8	Low	Clean crown of dead wood and undertake aerial inspection of the crown
19	<i>Eucalyptus obliqua</i>	Yes	Normal	77	30	13	Low	Clean crown of dead wood and undertake an aerial inspection of the crown
21	<i>Eucalyptus obliqua</i>	Yes	Normal	45	20	6	Low	No action
22	<i>Eucalyptus obliqua</i>	No	Low	60	30	8	Low	Clean crown of dead wood and undertake an aerial inspection of the crown

134 Hereford Road, Mt Evelyn – Tree Risk Assessment

Appendix 1 Tree Risk Assessment Forms



Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 1/09/2022 Time 1:55:00 PM
 Address/ Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3797553, -37.76969164 Tree no. 3 Sheet of
 Tree species Eucalyptus obliqua dbh 80 cm Height 25 m Crown spread dia. 16 m
 Assessor(s) Tools used DBH tape, soil probe Time frame 2 years

Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 - rare 2 - occasional 3 - frequent 4 - constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3	N	N
2	House	Other trees		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	4	N	N
3	Cars		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3	N	N
4	People using yard		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	2	N	N

Site Factors

History of failures Yes Topography Flat Slope 10% Aspect South
 Site changes None Grade change Site clearing Changed soil hydrology Root cuts Describe
 Soil conditions Limited volume Saturated Shallow Compacted Pavement over roots 50 % Describe Gravel driveway
 Prevailing wind direction SW Common weather Strong winds Ice Snow Heavy rain Describe

Tree Health and Species Profile

Vigor Low Normal High Foliage None (seasonal) None (dead) Normal 90 % Chlorotic % Necrotic %
 Pests/Biotic Abiotic
 Species failure profile Branches Trunk Roots Describe

Load Factors

Wind exposure Protected Partial Full Wind funneling Relative crown size Small Medium Large
 Crown density Sparse Normal Dense Interior branches Few Normal Dense Vines/Mistletoe/Moss
 Recent or expected change in load factors

Tree Defects and Conditions Affecting the Likelihood of Failure

— Crown and Branches —

Unbalanced crown LCR 40 %
 Dead twigs/branches 5 % overall Max. dia. 150mm
 Broken/Hangers Number Max. dia.
 Over-extended branches
 Pruning history
 Crown cleaned Thinned Raised
 Reduced Topped Lion-tailed
 Flush cuts Other
 Branch failure Condition (s) of concern
 Cracks Lightning damage
 Codominant Included bark
 Weak attachments Cavity/Nest hole % circ.
 Previous branch failures Similar branches present
 Dead/Missing bark Cankers/Galls/Burls Sapwood damage/decay
 Conks Heartwood decay
 Response growth

Part Size 300mm Fall Distance 25m
 Load on defect N/A Minor Moderate Significant
 Likelihood of failure Improbable Possible Probable Imminent
 Part Size Fall Distance
 Load on defect N/A Minor Moderate Significant
 Likelihood of failure Improbable Possible Probable Imminent

— Trunk —

Dead/Missing bark Abnormal bark texture/color
 Codominant stems Included bark Cracks
 Sapwood damage/decay Cankers/Galls/Burls Sap ooze
 Lightning damage Heartwood decay Conks/Mushrooms
 Cavity/Nest hole % circ. Depth Poor taper
 Lean 5 ° Corrected? No - phototropic/lean
 Response growth Yes, around stem union and sapwood damage
 Condition (s) of concern Stem union failure
 Part Size 400mm Fall Distance 15m
 Load on defect N/A Minor Moderate Significant
 Likelihood of failure Improbable Possible Probable Imminent

— Roots and Root Collar —


Collar buried/Not visible Depth Stem girdling
 Dead Decay Conks/Mushrooms
 Ooze Cavity % circ.
 Cracks Cut/Damaged roots Distance from trunk in SRZ
 Root plate lifting Soil weakness
 Response growth
 Condition (s) of concern Root plate failure
 Part Size whole tree Fall Distance 25m
 Load on defect N/A Minor Moderate Significant
 Likelihood of failure Improbable Possible Probable Imminent

Risk Categorization

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>						
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>													
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe					
People in house	Branch	Failure			✓													✓					L	
	Stem union		✓																✓				L	
	Root plate			✓																			✓	L
House	Branch	Failure			✓																		✓	L
	Stem union		✓																	✓				L
	Root plate			✓																		✓		L
Cars	Branch	Failure			✓						✓												✓	L
	Stem union		✓									✓											✓	L
	Root plate			✓									✓										✓	L
People using front yard	Branch	Failure			✓																		✓	L
	Stem union		✓																				✓	L
	Root plate			✓																			✓	L


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



Notes, explanations, descriptions

Mitigation options

1. Periodic re-inspection Residual risk Low

2. _____ Residual risk _____

3. _____ Residual risk _____

4. _____ Residual risk _____

Overall tree risk rating Low Moderate High Extreme

Overall residual risk None Low Moderate High Extreme **Recommended inspection interval** 2 years

Data Final Preliminary **Advanced assessment needed** No Yes-Type/Reason _____

Inspection limitations None Visibility Access Vines Root collar buried Describe Inspection undertaken from ground level only



Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 1/09/2022 Time 2:07:00 PM
 Address/ Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3797886, -37.769691 Tree no. 4 Sheet of
 Tree species Eucalyptus obliqua dbh 70 cm Height 30 m Crown spread dia. 9 m
 Assessor(s) Tools used DBH tape, soil probe Time frame 2 years

Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 - rare 2 - occasional 3 - frequent 4 - constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House		✓	✓	3	N	N
2	House	Other trees		✓	✓	4	N	N
3	Cars		✓	✓	✓	3	N	N
4	People using yard		✓	✓	✓	2	N	N

Site Factors

History of failures Yes Topography Flat Slope 10% Aspect South
 Site changes None Grade change Site clearing Changed soil hydrology Root cuts Describe
 Soil conditions Limited volume Saturated Shallow Compacted Pavement over roots 75 % Describe Gravel road and driveway
 Prevailing wind direction SW Common weather Strong winds Ice Snow Heavy rain Describe

Tree Health and Species Profile

Vigor Low Normal High Foliage None (seasonal) None (dead) Normal 90 % Chlorotic % Necrotic %
 Pests/Biotic Abiotic
 Species failure profile Branches Trunk Roots Describe

Load Factors

Wind exposure Protected Partial Full Wind funneling Relative crown size Small Medium Large
 Crown density Sparse Normal Dense Interior branches Few Normal Dense Vines/Mistletoe/Moss
 Recent or expected change in load factors

Tree Defects and Conditions Affecting the Likelihood of Failure

— Crown and Branches —

Unbalanced crown LCR 25 %
 Dead twigs/branches 5 % overall Max. dia. 100mm
 Broken/Hangers Number Max. dia.
 Over-extended branches
 Pruning history
 Crown cleaned Thinned Raised
 Reduced Topped Lion-tailed
 Flush cuts Other
 Branch failure Condition (s) of concern
 Part Size 200mm Fall Distance 30m
 Load on defect N/A Minor Moderate Significant
 Likelihood of failure Improbable Possible Probable Imminent
 Cracks Lightning damage
 Codominant Included bark
 Weak attachments Cavity/Nest hole % circ.
 Previous branch failures Similar branches present
 Dead/Missing bark Cankers/Galls/Burls Sapwood damage/decay
 Conks Heartwood decay
 Response growth

— Trunk —

Dead/Missing bark Abnormal bark texture/color
 Codominant stems Included bark Cracks
 Sapwood damage/decay Cankers/Galls/Burls Sap ooze
 Lightning damage Heartwood decay Conks/Mushrooms
 Cavity/Nest hole % circ. Depth Poor taper
 Lean 3 ° Corrected? Yes
 Response growth Yes, around sapwood damage
 Condition (s) of concern
 Part Size Fall Distance
 Load on defect N/A Minor Moderate Significant
 Likelihood of failure Improbable Possible Probable Imminent

— Roots and Root Collar —


Collar buried/Not visible Depth Stem girdling
 Dead Decay Conks/Mushrooms
 Ooze Cavity % circ.
 Cracks Cut/Damaged roots Distance from trunk in SRZ
 Root plate lifting Soil weakness
 Response growth
 Condition (s) of concern Root plate failure
 Part Size whole tree Fall Distance 30m
 Load on defect N/A Minor Moderate Significant
 Likelihood of failure Improbable Possible Probable Imminent

Risk Categorization

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>						
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>													
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe					
People in house	Branch Root plate	Failure		✓													✓					L		
				✓																			✓	L
House	Branch Root plate	Failure		✓														✓					L	
				✓																	✓			
Cars	Branch Root plate	Failure		✓							✓								✓				L	
				✓								✓									✓			
People using front yard	Branch Root plate	Failure		✓																			✓	L
				✓																				


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



Notes, explanations, descriptions

Mitigation options

1. Periodic re-inspection

Residual risk Low

2. _____

Residual risk _____

3. _____

Residual risk _____

4. _____

Residual risk _____

Overall tree risk rating Low Moderate High Extreme

Overall residual risk None Low Moderate High Extreme

Recommended inspection interval 2 years

Data Final Preliminary **Advanced assessment needed** No Yes-Type/Reason _____

Inspection limitations None Visibility Access Vines Root collar buried Describe Inspection undertaken from ground level only



Basic Tree Risk Assessment Form

Date 1/09/2022Time 2:52:00 PMClient Yarra Ranges CouncilTree no. 8Address/ Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3796618, -37.76959311Sheet of Tree species Eucalyptus obliquadbh 66 cmHeight 30 mCrown spread dia. 14 mAssessor(s) Tools used DBH tape, soil probeTime frame 2 years

Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 - rare 2 - occasional 3 - frequent 4 - constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House		✓	✓	3	N	N
2	House			✓	✓	4	N	N
3	Cars		✓	✓	✓	3	N	N
4	People using yard		✓	✓	✓	2	N	N

Site Factors

History of failures Yes Topography Flat Slope 10% Aspect SouthSite changes None Grade change Site clearing Changed soil hydrology Root cuts Describe Soil conditions Limited volume Saturated Shallow Compacted Pavement over roots 50 % Describe Conc. pad & gravel drivewayPrevailing wind direction SW Common weather Strong winds Ice Snow Heavy rain Describe

Tree Health and Species Profile

Vigor Low Normal High Foliage None (seasonal) None (dead) Normal 90 % Chlorotic % Necrotic %Pests/Biotic Abiotic Species failure profile Branches Trunk Roots Describe

Load Factors

Wind exposure Protected Partial Full Wind funneling Relative crown size Small Medium Large Crown density Sparse Normal Dense Interior branches Few Normal Dense Vines/Mistletoe/Moss Recent or expected change in load factors

Tree Defects and Conditions Affecting the Likelihood of Failure

— Crown and Branches —

Unbalanced crown LCR 30 %
 Dead twigs/branches 10 % overall Max. dia. 100 mm
 Broken/Hangers Number Max. dia.
 Over-extended branches
 Pruning history
 Crown cleaned Thinned Raised
 Reduced Topped Lion-tailed
 Flush cuts Other
 Branch failure Condition (s) of concern

Part Size 200 mm dia. Fall Distance 30 m
 Load on defect N/A Minor Moderate Significant
 Likelihood of failure Improbable Possible Probable Imminent

— Trunk —

Dead/Missing bark Abnormal bark texture/color
 Codominant stems Included bark Cracks
 Sapwood damage/decay Cankers/Galls/Burls Sap ooze
 Lightning damage Heartwood decay Conks/Mushrooms
 Cavity/Nest hole % circ. Depth Poor taper
 Lean 5 ° Corrected? Yes
 Response growth Yes, above buttress root
 Condition (s) of concern

Part Size Fall Distance
 Load on defect N/A Minor Moderate Significant
 Likelihood of failure Improbable Possible Probable Imminent

— Roots and Root Collar —

Collar buried/Not visible Depth Stem girdling
 Dead Decay Conks/Mushrooms
 Ooze Cavity % circ.
 Cracks Cut/Damaged roots Distance from trunk in SRZ
 Root plate lifting Soil weakness
 Response growth
 Condition (s) of concern Root plate failure


Part Size Whole tree Fall Distance 30 m
 Load on defect N/A Minor Moderate Significant
 Likelihood of failure Improbable Possible Probable Imminent

Risk Categorization

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>			
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>										
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe		
People in house	Branch Root plate	Failure		✓			✓					✓				✓					L
				✓					✓			✓								✓	
House	Branch Root plate	Failure		✓			✓					✓				✓					L
				✓					✓		✓							✓			
Cars	Branch Root plate	Failure		✓						✓			✓			✓					L
				✓					✓		✓						✓				
People using front yard	Branch Root plate	Failure		✓				✓				✓								✓	L
				✓				✓			✓									✓	


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



Notes, explanations, descriptions

Mitigation options

1. Periodic re-inspection
2. _____
3. _____
4. _____

Residual risk Low

Residual risk _____

Residual risk _____

Residual risk _____

Overall tree risk rating Low Moderate High Extreme

Overall residual risk None Low Moderate High Extreme **Recommended inspection interval** 2 years

Data Final Preliminary **Advanced assessment needed** No Yes-Type/Reason _____

Inspection limitations None Visibility Access Vines Root collar buried Describe Inspection undertaken from ground level only

Risk Categorization


Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>			
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>										
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe		
People in house	Branch Root plate	Failure			✓		✓					✓						✓		L	
				✓						✓			✓						✓		L
House	Branch Root plate	Failure			✓			✓				✓					✓			L	
				✓						✓			✓						✓		L
People using yard	Branch Root plate	Failure			✓			✓				✓							✓		L
				✓						✓			✓							✓	

Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely

Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



Notes, explanations, descriptions

Mitigation options

1. Periodic re-inspection
2. Clean crown of dead wood
3. _____
4. _____

Residual risk Low

Residual risk Low

Residual risk _____

Residual risk _____

Overall tree risk rating Low Moderate High Extreme

Overall residual risk None Low Moderate High Extreme

Recommended inspection interval 2 years

Data Final Preliminary **Advanced assessment needed** No Yes-Type/Reason Aerial inspection of crown to check for weak branch attachments

Inspection limitations None Visibility Access Vines Root collar buried Describe Inspection undertaken from ground level only



Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 6/09/2022 Time 9:15:00 AM
 Address/ Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3794601, -37.76967431 Tree no. 17 Sheet of
 Tree species Eucalyptus gonicalyx dbh 70 cm Height 25 m Crown spread dia. 8 m
 Assessor(s) Tools used DBH tape, soil probe Time frame 2 years

Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 - rare 2 - occasional 3 - frequent 4 - constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3	N	N
2	House		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	4	N	N
3	People using yard		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	2	N	N
4								

Site Factors

History of failures Yes Topography Flat Slope 10% Aspect South
 Site changes None Grade change Site clearing Changed soil hydrology Root cuts Describe
 Soil conditions Limited volume Saturated Shallow Compacted Pavement over roots <10% Describe Concrete slab in SRZ
 Prevailing wind direction SW Common weather Strong winds Ice Snow Heavy rain Describe

Tree Health and Species Profile

Vigor Low Normal High Foliage None (seasonal) None (dead) Normal 90 % Chlorotic % Necrotic %
 Pests/Biotic Abiotic
 Species failure profile Branches Trunk Roots Describe

Load Factors

Wind exposure Protected Partial Full Wind funneling Relative crown size Small Medium Large
 Crown density Sparse Normal Dense Interior branches Few Normal Dense Vines/Mistletoe/Moss
 Recent or expected change in load factors

Tree Defects and Conditions Affecting the Likelihood of Failure

— Crown and Branches —

Unbalanced crown LCR 20 %
 Dead twigs/branches 10 % overall Max. dia. 150 mm
 Broken/Hangers Number Max. dia.
 Over-extended branches
 Pruning history
 Crown cleaned Thinned Raised
 Reduced Topped Lion-tailed
 Flush cuts Other
 Cracks Lightning damage
 Codominant Included bark
 Weak attachments Cavity/Nest hole % circ.
 Previous branch failures Similar branches present
 Dead/Missing bark Cankers/Galls/Burls Sapwood damage/decay
 Conks Heartwood decay
 Response growth
 Branch failure Condition (s) of concern

Part Size 150 mm dia. Fall Distance 25 m
 Load on defect N/A Minor Moderate Significant
 Likelihood of failure Improbable Possible Probable Imminent
 Part Size Fall Distance
 Load on defect N/A Minor Moderate Significant
 Likelihood of failure Improbable Possible Probable Imminent

— Trunk —

Dead/Missing bark Abnormal bark texture/color
 Codominant stems Included bark Cracks
 Sapwood damage/decay Cankers/Galls/Burls Sap ooze
 Lightning damage Heartwood decay Conks/Mushrooms
 Cavity/Nest hole % circ. Depth Poor taper Lean 2 ° Corrected? No
 Response growth
 Condition (s) of concern
 Part Size Fall Distance
 Load on defect N/A Minor Moderate Significant
 Likelihood of failure Improbable Possible Probable Imminent

— Roots and Root Collar —

Collar buried/Not visible Depth Stem girdling
 Dead Decay Conks/Mushrooms
 Ooze Cavity % circ.
 Cracks Cut/Damaged roots Distance from trunk in SRZ
 Root plate lifting Soil weakness
 Response growth
 Condition (s) of concern Root plate failure
 Part Size Whole tree Fall Distance 25 m
 Load on defect N/A Minor Moderate Significant
 Likelihood of failure Improbable Possible Probable Imminent

Risk Categorization


Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>			
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>										
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe		
People in house	Branch Root plate	Failure			✓		✓					✓							✓		L
				✓					✓		✓									✓	
House	Branch Root plate	Failure			✓				✓			✓				✓					L
				✓					✓		✓								✓		
People using yard	Branch Root plate	Failure			✓		✓				✓								✓		L
				✓			✓				✓								✓		

Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely

Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



Notes, explanations, descriptions

Mitigation options

1. Periodic re-inspection
2. Clean crown of dead wood
3. _____
4. _____

Residual risk Low

Residual risk Low

Residual risk _____

Residual risk _____

Overall tree risk rating Low Moderate High Extreme

Overall residual risk None Low Moderate High Extreme **Recommended inspection interval** 2 years

Data Final Preliminary **Advanced assessment needed** No Yes-Type/Reason Aerial inspection of crown to check for weak branch attachments

Inspection limitations None Visibility Access Vines Root collar buried Describe Inspection undertaken from ground level only

Risk Categorization


Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>			
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>										
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe		
People in house	Branch Root plate	Failure			✓			✓				✓					✓				L
				✓						✓		✓								✓	
House	Branch Root plate	Failure			✓				✓			✓					✓				L
				✓						✓		✓							✓		
People using yard	Branch Root plate	Failure			✓			✓			✓								✓		L
				✓				✓			✓								✓		

Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely

Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



Notes, explanations, descriptions

Mitigation options

1. Periodic re-inspection Residual risk Low
2. Clean crown of dead wood Residual risk Low
3. _____ Residual risk _____
4. _____ Residual risk _____

Overall tree risk rating Low Moderate High Extreme

Overall residual risk None Low Moderate High Extreme **Recommended inspection interval** _____

Data Final Preliminary **Advanced assessment needed** No Yes-Type/Reason Aerial inspection of crown to check for weak branch attachments

Inspection limitations None Visibility Access Vines Root collar buried Describe Inspection undertaken from ground level only



Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 6/09/2022 Time 10:08:00 AM
 Address/ Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3793413, -37.76972934 Tree no. 22 Sheet of
 Tree species Eucalyptus obliqua dbh 60 cm Height 30 m Crown spread dia. 8 m
 Assessor(s) Tools used DBH tape, soil probe Time frame 2 years

Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3	N	N
2	House	Other trees		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	4	N	N
3	People using yard		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	2	N	N
4								

Site Factors

History of failures Yes Topography Flat Slope 10% Aspect South
 Site changes None Grade change Site clearing Changed soil hydrology Root cuts Describe
 Soil conditions Limited volume Saturated Shallow Compacted Pavement over roots % Describe
 Prevailing wind direction SW Common weather Strong winds Ice Snow Heavy rain Describe

Tree Health and Species Profile

Vigor Low Normal High Foliage None (seasonal) None (dead) Normal 90% Chlorotic % Necrotic %
 Pests/Biotic Abiotic
 Species failure profile Branches Trunk Roots Describe

Load Factors

Wind exposure Protected Partial Full Wind funneling Relative crown size Small Medium Large
 Crown density Sparse Normal Dense Interior branches Few Normal Dense Vines/Mistletoe/Moss
 Recent or expected change in load factors

Tree Defects and Conditions Affecting the Likelihood of Failure

— Crown and Branches —

Unbalanced crown LCR 25% Cracks Lightning damage
 Dead twigs/branches 20% overall Max. dia. 150 mm Codominant Included bark
 Broken/Hangers Number Max. dia. Weak attachments Cavity/Nest hole % circ.
 Over-extended branches Previous branch failures Similar branches present
Pruning history Dead/Missing bark Cankers/Galls/Burls Sapwood damage/decay
 Crown cleaned Thinned Raised Conks Heartwood decay
 Reduced Topped Lion-tailed Response growth
 Flush cuts Other
 Branch failure Condition (s) of concern

Part Size 150 mm dia. Fall Distance 30 m Part Size Fall Distance
 Load on defect N/A Minor Moderate Significant Load on defect N/A Minor Moderate Significant
 Likelihood of failure Improbable Possible Probable Imminent Likelihood of failure Improbable Possible Probable Imminent

— Trunk —

Dead/Missing bark Abnormal bark texture/color
 Codominant stems Included bark Cracks
 Sapwood damage/decay Cankers/Galls/Burls Sap ooze
 Lightning damage Heartwood decay Conks/Mushrooms
 Cavity/Nest hole % circ. Depth Poor taper
 Lean ° Corrected?
 Response growth
 Condition (s) of concern

Part Size Fall Distance
 Load on defect N/A Minor Moderate Significant
 Likelihood of failure Improbable Possible Probable Imminent

— Roots and Root Collar —

Collar buried/Not visible Depth Stem girdling
 Dead Decay Conks/Mushrooms
 Ooze Cavity % circ.
 Cracks Cut/Damaged roots Distance from trunk
 Root plate lifting Soil weakness
 Response growth
 Condition (s) of concern Root plate failure

Part Size Whole tree Fall Distance 30 m
 Load on defect N/A Minor Moderate Significant
 Likelihood of failure Improbable Possible Probable Imminent

Risk Categorization


Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>			
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>										
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe		
People in house	Branch Root plate	Failure			✓		✓					✓					✓				L
				✓					✓		✓									✓	
House	Branch Root plate	Failure			✓		✓					✓					✓				L
				✓					✓		✓								✓		
People using yard	Branch Root plate	Failure			✓		✓					✓							✓		L
				✓			✓				✓								✓		

Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely

Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



Notes, explanations, descriptions

Mitigation options

- Periodic re-inspection Residual risk Low
- Clean crown of dead wood Residual risk Low
- Residual risk _____
- Residual risk _____

Overall tree risk rating Low Moderate High Extreme

Overall residual risk None Low Moderate High Extreme **Recommended inspection interval** _____

Data Final Preliminary **Advanced assessment needed** No Yes-Type/Reason Aerial inspection of crown to check for weak branch attachments

Inspection limitations None Visibility Access Vines Root collar buried Describe Inspection undertaken from ground level only

