



# *Arborist Report*

*Tree Risk Assessment (TRA)*

*134 Hereford Road, Mt Evelyn*

Prepared by: Nicholas Magree  
(Grad Cert Arboriculture, ISA Tree Risk Assessment Qualified)  
Report Date: 28 September 2022

**Contents**

1. Summary of Assessment..... 1

2. Tree Plan ..... 2

3. Tree Assessment Table ..... 3

Appendix 1 Tree Risk Assessment Forms.....

## 1. Summary of Assessment

- 1.1 The scope of this report is to inspect trees in the road reserve (the site) and assess tree risk relative to the use of 134 Hereford Road, Mt Evelyn. During the course of the assessment, the site was attended on four occasions between 1/9/2022 – 27/9/2022. Trees have been tagged with identification numbers (numbered 1 to 25). Trees were assessed with the aid of a soil probe, diameter measuring tape, GIS software, camera phone and the ISA Tree Risk Assessment Form.
- 1.2 The site slopes down approximately 10 degrees to the south and is partially exposed to the prevailing south-westerly winds as well as easterly winds. The site is protected from northerly winds by a ridge line and tall trees on private property.
- 1.3 The house at 134 Hereford Road, Mt Evelyn, which is adjacent to the site, is nestled amongst a stand of mature eucalypt. Over time numerous trees in the road reserve bordering this property have been subjected to excavation, level changes, pavement and/or compaction within root zones.
- 1.4 At the time of the assessment parts of the site were very wet and subject to overland stormwater flows. In particular, the soils directly north of 134 Hereford Road and the table drain along the west side of Kookaburra Lane were saturated.
- 1.5 In the past 18 months a tree fell from the edge of the table drain on Kookaburra Lane and impacted the house at 134 Hereford Road, Mt Evelyn. Numerous other trees around the site and on adjoining private property have also fallen – many as a result of a severe storm event that impacted the Yarra Ranges in June 2021.
- 1.6 This report considers 25 trees in the road reserve. Risk assessments were undertaken by Nicholas Magree (Arborist) to determine risk ratings and suggest risk mitigation options for each tree (see appendix 1). Risk mitigation options were reviewed by the Coordinator of Trees (Paul Mechelen) and subsequent actions have been recommended (see section 3). Of the 25 trees assessed:
  - 12 trees are assessed as low risk with no further action recommended
  - 5 trees are assessed as low risk (preliminary). Further advanced assessments are required before these risk ratings are finalised
  - 1 tree (dead) is assessed as low risk and tree removal is recommended
  - 4 trees are assessed as moderate risk and tree removal is recommended
  - 1 tree is assessed as moderate risk and branch removal is recommended
  - 2 trees are assessed as high risk and tree removal is recommended.

## 2. Tree Plan



### 3 Tree Assessment Table

Tree No.	Botanic Name	Tree within 10m of dwelling?	Vitality	DBH (cm)	Height (m)	Spread dia. (m)	Overall Risk	Recommended Action
1	<i>Eucalyptus obliqua</i>	No	Normal	72	15	12	Low	No action
2	<i>Eucalyptus obliqua</i>	Yes	Normal	53	20	8	<b>Moderate</b>	Tree removal
3	<i>Eucalyptus obliqua</i>	No	Normal	80	25	16	Low	No action
4	<i>Eucalyptus obliqua</i>	No	Normal	70	30	9	Low	No action
5	<i>Eucalyptus obliqua</i>	No	Low	69	30	7	<b>Moderate</b>	Tree removal
6	<i>Eucalyptus obliqua</i>	No	Low	34	10	10	Low	No action
7	<i>Eucalyptus obliqua</i>	No	Low	71	30	12	<b>Moderate</b>	Tree removal
8	<i>Eucalyptus obliqua</i>	No	Normal	66	30	14	Low	No action
9	<i>Eucalyptus obliqua</i>	No	Normal	28	8	3	Low	No action
10	<i>Eucalyptus obliqua</i>	No	Low	38	16	5	<b>Moderate</b>	Remove broken/hanging branch
11	<i>Eucalyptus obliqua</i>	No	Dead	25	8	0	Low	Tree removal
12	<i>Eucalyptus obliqua</i>	Yes	Normal	90	30	12	<b>Moderate</b>	Tree removal
13	<i>Eucalyptus obliqua</i>	Yes	Normal	44	20	8	<b>High</b>	Tree removal
14	<i>Eucalyptus goniocalyx</i>	No	Normal	39	15	13	Low	No action
15	<i>Eucalyptus obliqua</i>	No	Low	42	15	7	Low	No action
16	<i>Eucalyptus obliqua</i>	Yes	Normal	84	30	10	Low	Clean crown of dead wood and undertake aerial inspection of the crown

Tree No.	Botanic Name	Tree within 10m of dwelling?	Vitality	DBH (cm)	Height (m)	Spread dia. (m)	Overall Risk	Recommended Action
17	<i>Eucalyptus obliqua</i>	Yes	Low	70	25	8	Low	Clean crown of dead wood and undertake aerial inspection of the crown
18	<i>Eucalyptus goniacalyx</i>	Yes	Normal	45	15	7	<b>High</b>	Tree removal
19	<i>Eucalyptus obliqua</i>	Yes	Normal	77	30	13	Low	Clean crown of dead wood and undertake an aerial inspection of the crown
20	<i>Eucalyptus obliqua</i>	Yes	Normal	37	15	10	Low	No action
21	<i>Eucalyptus obliqua</i>	Yes	Normal	45	20	6	Low	No action
22	<i>Eucalyptus obliqua</i>	No	Low	60	30	8	Low	Clean crown of dead wood and undertake an aerial inspection of the crown
23	<i>Eucalyptus goniacalyx</i>	No	Normal	45	18	8	Low	No action
24	<i>Eucalyptus obliqua</i>	No	Normal	38	25	6	Low	No action
25	<i>Eucalyptus radiata</i>	No	High	90	30	20	Low	Undertake tomography to test the extent of decay in the stem above the stem union

## Appendix 1 Tree Risk Assessment Forms



# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 1/09/2022 Time 1:31:00 PM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.379699, -37.76976256 Tree no. 1 Sheet      of       
 Tree species Eucalyptus obliqua dbh 72 cm Height 15 m Crown spread dia. 12 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

## Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House		✓	✓	3	N	N
2	House			✓	✓	4	N	N
3	Electrical service wire		✓	✓	✓	4	N	N
4	People using yard		✓	✓	✓	2	N	N

## Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe       
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots  % Describe       
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

## Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

## Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

## Tree Defects and Conditions Affecting the Likelihood of Failure

### — Crown and Branches —

Unbalanced crown  LCR 50 %  
 Dead twigs/branches  10 % overall Max. dia. 150mm  
 Broken/Hangers Number      Max. dia.       
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Branch failure      Condition(s) of concern       
 Part Size 150mm Fall Distance 15m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent   
 Cracks  Lightning damage   
 Codominant  Included bark   
 Weak attachments  Cavity/Nest hole      % circ.  
 Previous branch failures  Similar branches present   
 Dead/Missing bark  Cankers/Galls/Burls  Sapwood damage/decay   
 Conks  Heartwood decay   
 Response growth     

### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean 2 ° Corrected? No - phototropic lean  
 Response growth       
 Condition(s) of concern Stem union failure  
 Part Size 400mm Fall Distance 15m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Roots and Root Collar —

Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity       % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk       
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size whole tree Fall Distance 15m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent




**Risk Categorization**

Target (Target number or description)	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating (from Matrix 2)				
			Failure				Impact				Failure & Impact (from Matrix 1)											
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe			
People in house	Branch	Failure		✓			✓					✓				✓					L	
	Stem			✓			✓					✓						✓				L
	Roots plate		✓				✓					✓							✓			L
House	Branch	Failure		✓			✓					✓					✓				L	
	Stem			✓			✓					✓							✓			L
	Root plate		✓				✓					✓							✓			L
Electrical service wire	Branch	Failure		✓				✓				✓					✓				L	
	Stem			✓					✓			✓		✓				✓				L
	Rootplate		✓						✓			✓						✓				L
People using yard	Branch	Failure		✓				✓				✓							✓		L	
	Stem			✓				✓				✓								✓		L
	Root plate		✓					✓				✓								✓		L


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---



---



---



---

**Mitigation options**

1. Periodic re-inspection Residual risk Low
2. \_\_\_\_\_ Residual risk \_\_\_\_\_
3. \_\_\_\_\_ Residual risk \_\_\_\_\_
4. \_\_\_\_\_ Residual risk \_\_\_\_\_

**Overall tree risk rating**      Low     Moderate     High     Extreme

**Overall residual risk**    None     Low     Moderate     High     Extreme       **Recommended inspection interval** 2 years

**Data**  Final     Preliminary    **Advanced assessment needed**  No     Yes-Type/Reason \_\_\_\_\_

**Inspection limitations**     None     Visibility     Access     Vines     Root collar buried    Describe Inspection undertaken from ground level only



# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 1/09/2022 Time 1:43:00 PM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3797176, -37.76970076 Tree no. 2 Sheet      of       
 Tree species Eucalyptus obliqua dbh 53 cm Height 20 m Crown spread dia. 8 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

## Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House		✓	✓	3	N	N
2	House			✓	✓	4	N	N
3	Cars		✓	✓	✓	3	N	N
4	People using yard		✓	✓	✓	2	N	N

## Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe       
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots  50 % Describe Gravel driveway  
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

## Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

## Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

## Tree Defects and Conditions Affecting the Likelihood of Failure

### — Crown and Branches —

Unbalanced crown  LCR 25 %  
 Dead twigs/branches  5 % overall Max. dia. 100mm  
 Broken/Hangers Number      Max. dia.       
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Branch failure      Condition(s) of concern       
 Part Size 200 mm dia. Fall Distance 20m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent   
 Cracks  Lightning damage   
 Codominant  Included bark   
 Weak attachments  Cavity/Nest hole      % circ.  
 Previous branch failures  Similar branches present   
 Dead/Missing bark  Cankers/Galls/Burls  Sapwood damage/decay   
 Conks  Heartwood decay   
 Response growth     

### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean      ° Corrected?       
 Response growth       
 Condition(s) of concern       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Roots and Root Collar —


Collar buried/Not visible  Depth 100 mm Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity       % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk in SRZ  
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size Whole tree Fall Distance 20m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### Risk Categorization

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>			
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>										
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe		
People in house	Branch Root plate	Failure		✓			✓				✓			✓							L
				✓					✓		✓									✓	L
House	Branch Root plate	Failure		✓				✓			✓				✓						L
				✓					✓		✓					✓					M
Cars	Branch Root plate	Failure		✓						✓		✓			✓						L
				✓				✓		✓				✓							L
People using front yard	Branch Root plate	Failure		✓				✓			✓								✓		L
				✓				✓		✓									✓		L


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---

---

---

---

---

**Mitigation options**

1. [Periodic re-inspection](#) Residual risk [Moderate](#)
2. [Tree removal](#) Residual risk [None](#)
3. Residual risk \_\_\_\_\_
4. Residual risk \_\_\_\_\_

**Overall tree risk rating**      Low     Moderate     High     Extreme

**Overall residual risk**    None     Low     Moderate     High     Extreme       **Recommended inspection interval** [2 years](#)

**Data** Final    Preliminary    **Advanced assessment needed** No    Yes-Type/Reason \_\_\_\_\_

**Inspection limitations**    None    Visibility    Access    Vines    Root collar buried    Describe [Inspection undertaken from ground level only](#)



# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 1/09/2022 Time 1:55:00 PM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3797553, -37.76969164 Tree no. 3 Sheet      of       
 Tree species Eucalyptus obliqua dbh 80 cm Height 25 m Crown spread dia. 16 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

## Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3	N	N
2	House	Other trees		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	4	N	N
3	Cars		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3	N	N
4	People using yard		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	2	N	N

## Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe       
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots  50 % Describe Gravel driveway  
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

## Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

## Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

## Tree Defects and Conditions Affecting the Likelihood of Failure

### — Crown and Branches —

Unbalanced crown  LCR 40 %  
 Dead twigs/branches  5 % overall Max. dia. 150mm  
 Broken/Hangers Number      Max. dia.       
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Cracks  Lightning damage   
 Codominant  Included bark   
 Weak attachments  Cavity/Nest hole      % circ.  
 Previous branch failures  Similar branches present   
 Dead/Missing bark  Cankers/Galls/Burls  Sapwood damage/decay   
 Conks  Heartwood decay   
 Response growth       
 Condition(s) of concern       
 Part Size 300mm Fall Distance 25m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean 5 ° Corrected? No - phototropic lean  
 Response growth Yes, around stem union and sapwood damage  
 Condition(s) of concern Stem union failure  
 Part Size 400mm Fall Distance 15m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Roots and Root Collar —


Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity       % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk in SRZ  
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size whole tree Fall Distance 25m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### Risk Categorization

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>					
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>												
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe				
People in house	Branch	Failure			✓								✓				✓					L	
	Stem union		✓				✓						✓					✓					L
	Root plate			✓				✓					✓							✓			L
House	Branch	Failure			✓								✓					✓					L
	Stem union		✓				✓						✓					✓					L
	Root plate			✓				✓					✓							✓			L
Cars	Branch	Failure			✓					✓				✓				✓					L
	Stem union		✓					✓					✓					✓					L
	Root plate			✓				✓					✓						✓				L
People using front yard	Branch	Failure			✓								✓								✓		L
	Stem union		✓					✓					✓								✓		L
	Root plate			✓				✓					✓								✓		L


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---

---

---

---

---

**Mitigation options**

1. Periodic re-inspection Residual risk Low

2. \_\_\_\_\_ Residual risk \_\_\_\_\_

3. \_\_\_\_\_ Residual risk \_\_\_\_\_

4. \_\_\_\_\_ Residual risk \_\_\_\_\_

**Overall tree risk rating**      Low     Moderate     High     Extreme

**Overall residual risk**    None     Low     Moderate     High     Extreme       **Recommended inspection interval** 2 years

**Data** Final    Preliminary    **Advanced assessment needed** No    Yes-Type/Reason \_\_\_\_\_

**Inspection limitations**    None    Visibility    Access    Vines    Root collar buried    Describe Inspection undertaken from ground level only



# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 1/09/2022 Time 2:07:00 PM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3797886, -37.769691 Tree no. 4 Sheet      of       
 Tree species Eucalyptus obliqua dbh 70 cm Height 30 m Crown spread dia. 9 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

## Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House		✓	✓	3	N	N
2	House	Other trees		✓	✓	4	N	N
3	Cars		✓	✓	✓	3	N	N
4	People using yard		✓	✓	✓	2	N	N

## Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe       
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots  75 % Describe Gravel road and driveway  
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

## Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

## Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

## Tree Defects and Conditions Affecting the Likelihood of Failure

### — Crown and Branches —

Unbalanced crown  LCR 25 %  
 Dead twigs/branches  5 % overall Max. dia. 100mm  
 Broken/Hangers Number      Max. dia.       
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Branch failure      Condition(s) of concern       
 Part Size 200mm Fall Distance 30m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean 3 ° Corrected? Yes  
 Response growth Yes, around sapwood damage  
 Condition(s) of concern       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Roots and Root Collar —

Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity       % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk in SRZ  
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size whole tree Fall Distance 30m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

**Risk Categorization**

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>			
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>										
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe		
People in house	Branch Root plate	Failure		✓			✓				✓			✓							L
				✓				✓			✓									✓	L
House	Branch Root plate	Failure		✓				✓				✓				✓					L
				✓				✓			✓					✓					L
Cars	Branch Root plate	Failure		✓					✓			✓				✓					L
				✓						✓		✓				✓					L
People using front yard	Branch Root plate	Failure		✓				✓				✓							✓		L
				✓				✓			✓								✓		L


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---



---



---



---

**Mitigation options**

1. Periodic re-inspection Residual risk Low
2. \_\_\_\_\_ Residual risk \_\_\_\_\_
3. \_\_\_\_\_ Residual risk \_\_\_\_\_
4. \_\_\_\_\_ Residual risk \_\_\_\_\_

**Overall tree risk rating**      Low     Moderate     High     Extreme

**Overall residual risk**    None     Low     Moderate     High     Extreme       **Recommended inspection interval** 2 years

**Data** Final    Preliminary    **Advanced assessment needed** No    Yes-Type/Reason \_\_\_\_\_

**Inspection limitations**    None    Visibility    Access    Vines    Root collar buried    Describe Inspection undertaken from ground level only





# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 1/09/2022 Time 2:21:00 PM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3797391, -37.76958349 Tree no. 5 Sheet      of       
 Tree species Eucalyptus obliqua dbh 69 cm Height 30 m Crown spread dia. 7 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

## Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3	N	N
2	House	Other trees		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	4	N	N
3	Cars		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3	N	N
4	People using yard		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	2	N	N

## Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe       
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots  90 % Describe Gravel road and driveway  
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

## Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

## Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

## Tree Defects and Conditions Affecting the Likelihood of Failure

### — Crown and Branches —

Unbalanced crown  LCR 25 %  
 Dead twigs/branches  30 % overall Max. dia. 200mm  
 Broken/Hangers Number      Max. dia.       
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Branch failure      Condition(s) of concern       
 Part Size 200mm Fall Distance 30m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent   
 Cracks  Lightning damage   
 Codominant  Included bark   
 Weak attachments  Cavity/Nest hole      % circ.  
 Previous branch failures  Similar branches present   
 Dead/Missing bark  Cankers/Galls/Burls  Sapwood damage/decay   
 Conks  Heartwood decay   
 Response growth       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean      ° Corrected?       
 Response growth       
 Condition(s) of concern       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Roots and Root Collar —

Collar buried/Not visible  Depth 200mm (north) Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity       % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk in SRZ  
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size whole tree Fall Distance 30m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent




**Risk Categorization**

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>		
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>									
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe	
People in house	Branch Root plate	Failure			✓		✓					✓			✓					L
					✓			✓			✓								✓	L
House	Branch Root plate	Failure			✓		✓					✓				✓				L
					✓				✓			✓					✓			M
Cars	Branch Root plate	Failure			✓				✓				✓			✓				L
					✓				✓			✓				✓				L
People using front yard	Branch Root plate	Failure			✓			✓				✓							✓	L
					✓			✓			✓								✓	L


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---



---



---



---

**Mitigation options**

1. Periodic re-inspection Residual risk Moderate
2. Tree removal Residual risk None
3. \_\_\_\_\_ Residual risk \_\_\_\_\_
4. \_\_\_\_\_ Residual risk \_\_\_\_\_

**Overall tree risk rating**      Low     Moderate     High     Extreme

**Overall residual risk**    None     Low     Moderate     High     Extreme       **Recommended inspection interval** \_\_\_\_\_

**Data** Final    Preliminary    **Advanced assessment needed** No    Yes-Type/Reason \_\_\_\_\_

**Inspection limitations**    None    Visibility    Access    Vines    Root collar buried    Describe Inspection undertaken from ground level only



# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 1/09/2022 Time 2:27:00 PM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3797402, -37.76958443 Tree no. 6 Sheet      of       
 Tree species Eucalyptus obliqua dbh 34 cm Height 10 m Crown spread dia. 10 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

## Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	Cars		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3	N	N
2	People using yard		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	2	N	N
3								
4								

## Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe       
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots  70 % Describe Gravel road and driveway  
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

## Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

## Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

## Tree Defects and Conditions Affecting the Likelihood of Failure

### — Crown and Branches —

Unbalanced crown  LCR 25 %  
 Dead twigs/branches  5 % overall Max. dia. 50mm  
 Broken/Hangers Number      Max. dia.       
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Branch failure      Condition(s) of concern       
 Part Size 150mm dia. Fall Distance 10m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent   
 Cracks  Lightning damage   
 Codominant  Included bark   
 Weak attachments  Cavity/Nest hole      % circ.  
 Previous branch failures  Similar branches present   
 Dead/Missing bark  Cankers/Galls/Burls  Sapwood damage/decay   
 Conks  Heartwood decay   
 Response growth     

### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean 5 ° Corrected? No - phototropic lean  
 Response growth       
 Condition(s) of concern       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Roots and Root Collar —


Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity       % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk in SRZ  
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size Whole tree Fall Distance 10m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

**Risk Categorization**

Target (Target number or description)	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating (from Matrix 2)		
			Failure				Impact				Failure & Impact (from Matrix 1)									
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe	
Cars	Branch Root plate	Failure		✓						✓				✓				✓		L
				✓						✓				✓				✓		L
People using front yard	Branch Root plate	Failure		✓						✓				✓					✓	L
				✓						✓				✓				✓		L


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---



---



---



---

**Mitigation options**

1. Periodic re-inspection Residual risk Low

2. \_\_\_\_\_ Residual risk \_\_\_\_\_

3. \_\_\_\_\_ Residual risk \_\_\_\_\_

4. \_\_\_\_\_ Residual risk \_\_\_\_\_

**Overall tree risk rating**      Low     Moderate     High     Extreme

**Overall residual risk**    None     Low     Moderate     High     Extreme       **Recommended inspection interval** 2 years

**Data** Final    Preliminary    **Advanced assessment needed** No    Yes-Type/Reason \_\_\_\_\_

**Inspection limitations** None    Visibility    Access    Vines    Root collar buried    Describe Inspection undertaken from ground level only



# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 1/09/2022 Time 2:35:00 PM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3797064, -37.76950706 Tree no. 7 Sheet      of       
 Tree species Eucalyptus obliqua dbh 71 cm Height 30 m Crown spread dia. 12 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

## Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House		✓	✓	3	N	N
2	House	Other trees		✓	✓	4	N	N
3	Cars		✓	✓	✓	2	N	N
4	People using yard		✓	✓	✓	2	N	N

## Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe       
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots  30 % Describe Gravel driveway and road  
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

## Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

## Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

## Tree Defects and Conditions Affecting the Likelihood of Failure

### — Crown and Branches —

Unbalanced crown  LCR 50 %  
 Dead twigs/branches  10 % overall Max. dia. 200mm  
 Broken/Hangers Number      Max. dia.       
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Branch failure      Condition(s) of concern       
 Part Size 200mm Fall Distance 30m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean      ° Corrected?       
 Response growth wound wood has formed around column of decay  
 Condition(s) of concern       
 Part Size      Fall Distance 30 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Roots and Root Collar —


Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity       % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk in SRZ  
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size Whole tree Fall Distance 30m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

**Risk Categorization**

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>				
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>											
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe			
People in house	Branch Root plate	Failure			✓		✓					✓				✓					L	
					✓			✓				✓								✓		L
House	Branch Root plate	Failure			✓		✓					✓					✓				L	
					✓				✓			✓						✓				M
Cars	Branch Root plate	Failure			✓		✓				✓					✓					L	
					✓				✓			✓					✓					L
People using yard	Branch Root plate	Failure			✓		✓				✓									✓	L	
					✓		✓				✓									✓		L


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---



---



---



---

**Mitigation options**

1. Periodic re-inspection Residual risk Moderate
2. Tree removal Residual risk None
3. \_\_\_\_\_ Residual risk \_\_\_\_\_
4. \_\_\_\_\_ Residual risk \_\_\_\_\_

**Overall tree risk rating**      Low     Moderate     High     Extreme

**Overall residual risk**    None     Low     Moderate     High     Extreme       **Recommended inspection interval** 2 years

**Data** Final    Preliminary    **Advanced assessment needed** No    Yes-Type/Reason \_\_\_\_\_

**Inspection limitations**    None    Visibility    Access    Vines    Root collar buried    Describe Inspection undertaken from ground level only



# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 1/09/2022 Time 2:52:00 PM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3796618, -37.76959311 Tree no. 8 Sheet      of       
 Tree species Eucalyptus obliqua dbh 66 cm Height 30 m Crown spread dia. 14 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

## Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House		✓	✓	3	N	N
2	House			✓	✓	4	N	N
3	Cars		✓	✓	✓	3	N	N
4	People using yard		✓	✓	✓	2	N	N

## Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe       
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots  50 % Describe Conc. pad & gravel driveway  
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

## Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

## Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

## Tree Defects and Conditions Affecting the Likelihood of Failure

### — Crown and Branches —

Unbalanced crown  LCR 30 %  
 Dead twigs/branches  10 % overall Max. dia. 100 mm  
 Broken/Hangers Number      Max. dia.       
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Branch failure      Condition(s) of concern       
 Part Size 200 mm dia. Fall Distance 30 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent   
 Cracks  Lightning damage   
 Codominant  Included bark   
 Weak attachments  Cavity/Nest hole      % circ.  
 Previous branch failures  Similar branches present   
 Dead/Missing bark  Cankers/Galls/Burls  Sapwood damage/decay   
 Conks  Heartwood decay   
 Response growth     

### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean 5 ° Corrected? Yes  
 Response growth Yes, above buttress root  
 Condition(s) of concern       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Roots and Root Collar —


Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity       % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk in SRZ  
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size Whole tree Fall Distance 30 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

Risk Categorization

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>								
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>			Negligible	Minor	Significant	Severe									
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely						Very likely							
People in house	Branch Root plate	Failure		✓				✓					✓													L
				✓							✓			✓												
House	Branch Root plate	Failure		✓				✓					✓													L
				✓							✓			✓												
Cars	Branch Root plate	Failure		✓									✓													L
				✓							✓			✓												
People using front yard	Branch Root plate	Failure		✓									✓													L
				✓							✓			✓												


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



Notes, explanations, descriptions

---



---



---



---

Mitigation options

1. Periodic re-inspection Residual risk Low
2. \_\_\_\_\_ Residual risk \_\_\_\_\_
3. \_\_\_\_\_ Residual risk \_\_\_\_\_
4. \_\_\_\_\_ Residual risk \_\_\_\_\_

Overall tree risk rating      Low    Moderate    High    Extreme

Overall residual risk    None    Low    Moderate    High    Extreme       Recommended inspection interval 2 years

Data Final   Preliminary   Advanced assessment needed No   Yes-Type/Reason \_\_\_\_\_

Inspection limitations None   Visibility   Access   Vines   Root collar buried   Describe Inspection undertaken from ground level only





# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 1/09/2022 Time 2:59:00 PM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3796545, -37.76959519 Tree no. 9 Sheet      of       
 Tree species Eucalyptus obliqua dbh 28 cm Height 8 m Crown spread dia. 3 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

### Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House		✓	✓	3	N	N
2	House	Other trees		✓	✓	4	N	N
3	Cars			✓	✓	3	N	N
4	People using yard		✓	✓	✓	2	N	N

### Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe       
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots  5 % Describe Conc. pad  
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

### Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

### Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

### Tree Defects and Conditions Affecting the Likelihood of Failure

#### — Crown and Branches —

Unbalanced crown  LCR 30 %  
 Dead twigs/branches  30 % overall Max. dia. 100 mm  
 Broken/Hangers Number      Max. dia.       
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Branch failure      Condition(s) of concern       
 Part Size 100 mm dia. Fall Distance 8 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

Cracks  Lightning damage   
 Codominant  Included bark   
 Weak attachments  Cavity/Nest hole      % circ.  
 Previous branch failures  Similar branches present   
 Dead/Missing bark  Cankers/Galls/Burls  Sapwood damage/decay   
 Conks  Heartwood decay   
 Response growth     

Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

#### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean      ° Corrected?       
 Response growth       
 Condition(s) of concern       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

#### — Roots and Root Collar —

Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity       % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk       
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size Whole tree Fall Distance 8 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent




### Risk Categorization

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>	
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>								
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe
People in house	Branch Root plate	Failure	✓				✓				✓			✓					L
			✓				✓				✓			✓					L
House	Branch Root plate	Failure	✓				✓				✓			✓					L
			✓				✓				✓				✓				L
Cars	Branch Root plate	Failure	✓				✓				✓				✓				L
			✓					✓			✓				✓				L
People using front yard	Branch Root plate	Failure	✓				✓				✓					✓			L
			✓				✓				✓						✓		L


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---

---

---

---

---

**Mitigation options**

1. Periodic re-inspection Residual risk Low

2. \_\_\_\_\_ Residual risk \_\_\_\_\_

3. \_\_\_\_\_ Residual risk \_\_\_\_\_

4. \_\_\_\_\_ Residual risk \_\_\_\_\_

**Overall tree risk rating**      Low     Moderate     High     Extreme

**Overall residual risk**    None     Low     Moderate     High     Extreme       **Recommended inspection interval** 2 years

**Data** Final    Preliminary    **Advanced assessment needed** No    Yes-Type/Reason \_\_\_\_\_

**Inspection limitations**    None    Visibility    Access    Vines    Root collar buried    Describe Inspection undertaken from ground level only



# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 1/09/2022 Time 3:29:00 PM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.379579, -37.76956336 Tree no. 10 Sheet      of       
 Tree species Eucalyptus obliqua dbh 38 cm Height 16 m Crown spread dia. 5 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

## Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3	N	N
2	House	Other trees		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	4	N	N
3	Cars	Other trees			<input checked="" type="checkbox"/>	3	N	N
4	People using yard		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	2	N	N

## Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe       
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots  % Describe       
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

## Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

## Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

## Tree Defects and Conditions Affecting the Likelihood of Failure

### — Crown and Branches —

Unbalanced crown  LCR 25 %  
 Dead twigs/branches  30 % overall Max. dia. 100 mm  
 Broken/Hangers Number 1 Max. dia. 100 mm  
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Branch failure      Condition(s) of concern       
 Part Size 100 mm dia. Fall Distance 14 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

Cracks  Lightning damage   
 Codominant  Included bark   
 Weak attachments  Cavity/Nest hole      % circ.  
 Previous branch failures  Similar branches present   
 Dead/Missing bark  Cankers/Galls/Burls  Sapwood damage/decay   
 Conks  Heartwood decay   
 Response growth     

Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean      ° Corrected?       
 Response growth       
 Condition(s) of concern       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Roots and Root Collar —


Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity       % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk       
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size Whole tree Fall Distance 16 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### Risk Categorization

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>				
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>											
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe			
People in house	Branch	Failure				✓											✓					L
	Root plate			✓			✓							✓								✓
House	Branch	Failure				✓	✓						✓					✓				L
	Root plate			✓				✓					✓						✓			
Cars	Branch	Failure				✓	✓						✓					✓				L
	Root plate			✓				✓					✓					✓				
People using yard	Branch	Failure				✓		✓					✓						✓			M
	Root plate			✓				✓					✓							✓		


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---

---

---

---

---

**Mitigation options**

1. Remove broken/hanging branch Residual risk Low
2. Periodic re-inspection Residual risk Low
3. \_\_\_\_\_ Residual risk \_\_\_\_\_
4. \_\_\_\_\_ Residual risk \_\_\_\_\_

**Overall tree risk rating**      Low    Moderate    High    Extreme

**Overall residual risk**      None    Low    Moderate    High    Extreme       **Recommended inspection interval** 2 years

**Data**  Final    Preliminary   **Advanced assessment needed**  No    Yes-Type/Reason \_\_\_\_\_

**Inspection limitations**    None    Visibility    Access    Vines    Root collar buried   Describe Inspection undertaken from ground level only



# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 1/09/2022 Time 3:36:00 PM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3795712, -37.76956079 Tree no. 11 Sheet      of       
 Tree species Eucalyptus obliqua dbh 25 cm Height 8 m Crown spread dia. 0 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

### Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People using yard		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	2		N
2								
3								
4								

### Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe       
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots       % Describe       
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

### Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal      % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

### Load Factors

Wind exposure Protected  Partial  Full  Wind funneling       Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss        
 Recent or expected change in load factors     

### Tree Defects and Conditions Affecting the Likelihood of Failure

#### — Crown and Branches —

Unbalanced crown  LCR 0 %  
 Dead twigs/branches  100 % overall Max. dia. 150mm  
 Broken/Hangers Number      Max. dia.       
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Branch failure      Condition(s) of concern       
 Part Size 150mm Fall Distance 8 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

#### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean      ° Corrected?       
 Response growth       
 Condition(s) of concern       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

#### — Roots and Root Collar —


Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity       % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk       
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size Whole tree Fall Distance 8 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

**Risk Categorization**

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>			
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>										
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe		
People using front yard	Branch Root plate	Failure			✓													✓		L	
					✓														✓		L


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---



---



---



---

**Mitigation options**

1. Tree removal Residual risk None

2. \_\_\_\_\_ Residual risk \_\_\_\_\_

3. \_\_\_\_\_ Residual risk \_\_\_\_\_

4. \_\_\_\_\_ Residual risk \_\_\_\_\_

**Overall tree risk rating**      Low     Moderate     High     Extreme

**Overall residual risk**    None     Low     Moderate     High     Extreme       **Recommended inspection interval** \_\_\_\_\_

**Data** Final    Preliminary    **Advanced assessment needed** No    Yes-Type/Reason \_\_\_\_\_

**Inspection limitations**    None    Visibility    Access    Vines    Root collar buried    Describe Inspection undertaken from ground level only



# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 1/09/2022 Time 3:39:00 PM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3795934, -37.76961367 Tree no. 12 Sheet      of       
 Tree species Eucalyptus obliqua dbh 90 cm Height 30 m Crown spread dia. 12 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

## Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House		✓	✓	3	N	N
2	House	Other trees		✓	✓	4	N	N
3	Cars			✓	✓	3	N	N
4	People using yard		✓	✓	✓	2	N	N

## Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe Retaining wall  
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots  % Describe       
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

## Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

## Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

## Tree Defects and Conditions Affecting the Likelihood of Failure

### — Crown and Branches —

Unbalanced crown  LCR 30 %  
 Dead twigs/branches  25 % overall Max. dia. 200 mm  
 Broken/Hangers Number      Max. dia.       
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Branch failure      Condition(s) of concern       
 Part Size 200 mm dia. Fall Distance 30 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent   
 Cracks  Lightning damage   
 Codominant  Included bark   
 Weak attachments  Cavity/Nest hole      % circ.  
 Previous branch failures  Similar branches present   
 Dead/Missing bark  Cankers/Galls/Burls  Sapwood damage/decay   
 Conks  Heartwood decay   
 Response growth       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean      ° Corrected?       
 Response growth Yes, response growth at stem union  
 Condition(s) of concern Stem union failure  
 Part Size 400 mm dia. Fall Distance 30 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Roots and Root Collar —

Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity  % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk In TPZ  
 Root plate lifting  Soil weakness   
 Response growth Yes, wound wood on large surface root  
 Condition(s) of concern Root plate failure  
 Part Size Whole tree Fall Distance 30 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

**Risk Categorization**



Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>		
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>									
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe	
People in house	Branch	Failure			✓		✓					✓					✓			
	Stem union			✓				✓				✓							✓	
	Root plate			✓					✓			✓								✓
House	Branch	Failure			✓			✓				✓					✓			
	Stem union			✓					✓			✓						✓		
	Root plate			✓						✓		✓							✓	
Cars	Branch	Failure			✓		✓					✓					✓			
	Stem union			✓				✓				✓					✓			
	Root plate			✓					✓			✓					✓			
People using yard	Branch	Failure			✓			✓				✓							✓	
	Stem union			✓				✓				✓						✓		
	Root plate			✓				✓				✓						✓		

Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely

Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---



---



---



---

**Mitigation options**

- 1. [Periodic re-inspection](#) Residual risk [Moderate](#)
- 2. [Tree removal](#) Residual risk [None](#)
- 3. Residual risk \_\_\_\_\_
- 4. Residual risk \_\_\_\_\_

**Overall tree risk rating**      Low     Moderate     High     Extreme

**Overall residual risk**    None     Low     Moderate     High     Extreme       **Recommended inspection interval** [2 years](#)

**Data** Final    Preliminary    **Advanced assessment needed** No    Yes-Type/Reason \_\_\_\_\_

**Inspection limitations**    None    Visibility    Access    Vines    Root collar buried    Describe [Inspection undertaken from ground level only](#)





# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 1/09/2022 Time 3:47:00 PM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3795893, -37.76961964 Tree no. 13 Sheet      of       
 Tree species Eucalyptus obliqua dbh 44 cm Height 20 m Crown spread dia. 8 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

## Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3	N	N
2	House		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	4	N	N
3	Cars			<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3	N	N
4	People using yard		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	2	N	N

## Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe Retaining wall  
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots  % Describe       
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

## Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

## Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

## Tree Defects and Conditions Affecting the Likelihood of Failure

### — Crown and Branches —

Unbalanced crown  LCR 50 %  
 Dead twigs/branches  5 % overall Max. dia. 50 mm  
 Broken/Hangers Number      Max. dia.       
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Branch failure      Condition(s) of concern       
 Part Size 150 mm dia. Fall Distance 20 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent   
 Cracks  Lightning damage   
 Codominant  Included bark   
 Weak attachments  Cavity/Nest hole      % circ.  
 Previous branch failures  Similar branches present   
 Dead/Missing bark  Cankers/Galls/Burls  Sapwood damage/decay   
 Conks  Heartwood decay   
 Response growth     

### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean 3 ° Corrected? No - phototropic  
 Response growth       
 Condition(s) of concern       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Roots and Root Collar —

Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity  % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk in SRZ  
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size Whole tree Fall Distance 20 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent




**Risk Categorization**

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>				
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>											
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe			
People in house	Branch	Failure		✓									✓					✓				L
	Root plate				✓										✓						✓	
House	Branch	Failure		✓									✓					✓				L
	Root plate				✓										✓					✓		
Cars	Branch	Failure		✓				✓					✓					✓				L
	Root plate				✓				✓					✓					✓			
People using yard	Branch	Failure		✓									✓								✓	L
	Root plate				✓									✓							✓	


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---



---



---



---

**Mitigation options**

1. [Periodic re-inspection](#) Residual risk High
2. [Tree removal](#) Residual risk None
3. Residual risk \_\_\_\_\_
4. Residual risk \_\_\_\_\_

**Overall tree risk rating**      Low     Moderate     High     Extreme

**Overall residual risk**    None     Low     Moderate     High     Extreme       **Recommended inspection interval** 2 years

**Data** Final    Preliminary    **Advanced assessment needed** No    Yes-Type/Reason \_\_\_\_\_

**Inspection limitations**    None    Visibility    Access    Vines    Root collar buried    Describe Inspection undertaken from ground level only



# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 6/09/2022 Time 8:51:00 AM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3794819, -37.7695566 Tree no. 14 Sheet      of       
 Tree species Eucalyptus goniocalyx dbh 39 cm Height 15 m Crown spread dia. 13 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

## Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House			✓	3	N	N
2	House	Other trees			✓	4	N	N
3	People using yard		✓	✓	✓	2	N	N
4								

## Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe       
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots       % Describe       
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

## Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

## Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss        
 Recent or expected change in load factors     

## Tree Defects and Conditions Affecting the Likelihood of Failure

### — Crown and Branches —

Unbalanced crown  LCR 70 %  
 Dead twigs/branches  10 % overall Max. dia. 50 mm  
 Broken/Hangers Number      Max. dia.       
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Cracks  Lightning damage   
 Codominant  Included bark   
 Weak attachments  Cavity/Nest hole      % circ.  
 Previous branch failures  Similar branches present   
 Dead/Missing bark  Cankers/Galls/Burls  Sapwood damage/decay   
 Conks  Heartwood decay   
 Response growth       
 Condition(s) of concern       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean 3 ° Corrected? No - phototropic  
 Response growth       
 Condition(s) of concern       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Roots and Root Collar —


Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity       % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk       
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size Whole tree Fall Distance 15 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### Risk Categorization

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood												Consequences				Risk rating <i>(from Matrix 2)</i>
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>								
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant	Severe	
People in house	Root plate	Failure		✓			✓				✓				✓				L
House	Root plate	Failure		✓			✓				✓				✓				L
People using yard	Root plate	Failure		✓			✓				✓						✓		L


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
<b>Imminent</b>	Unlikely	Somewhat likely	Likely	Very likely
<b>Probable</b>	Unlikely	Unlikely	Somewhat likely	Likely
<b>Possible</b>	Unlikely	Unlikely	Unlikely	Somewhat likely
<b>Improbable</b>	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
<b>Very likely</b>	Low	Moderate	High	Extreme
<b>Likely</b>	Low	Moderate	High	High
<b>Somewhat likely</b>	Low	Low	Moderate	Moderate
<b>Unlikely</b>	Low	Low	Low	Low



**Notes, explanations, descriptions**

---



---



---



---

**Mitigation options**

1. Periodic re-inspection Residual risk Low

2. \_\_\_\_\_ Residual risk \_\_\_\_\_

3. \_\_\_\_\_ Residual risk \_\_\_\_\_

4. \_\_\_\_\_ Residual risk \_\_\_\_\_

**Overall tree risk rating**      Low     Moderate     High     Extreme

**Overall residual risk**    None     Low     Moderate     High     Extreme       **Recommended inspection interval** 2 years

**Data**  Final     Preliminary    **Advanced assessment needed**  No     Yes-Type/Reason \_\_\_\_\_

**Inspection limitations**     None     Visibility     Access     Vines     Root collar buried    Describe Inspection undertaken from ground level only



# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 6/09/2022 Time 8:57:00 AM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3794928, -37.76957067 Tree no. 15 Sheet      of       
 Tree species Eucalyptus obliqua dbh 42 cm Height 15 m Crown spread dia. 7m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

## Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House			✓	3	N	N
2	House	Other trees			✓	4	N	N
3	People using yard		✓	✓	✓	2	N	N
4							N	N

## Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe       
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots  % Describe       
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

## Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

## Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

## Tree Defects and Conditions Affecting the Likelihood of Failure

### — Crown and Branches —

Unbalanced crown  LCR 30 %  
 Dead twigs/branches  10 % overall Max. dia. 100 mm  
 Broken/Hangers Number      Max. dia.       
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Cracks  Lightning damage   
 Codominant  Included bark   
 Weak attachments  Cavity/Nest hole      % circ.  
 Previous branch failures  Similar branches present   
 Dead/Missing bark  Cankers/Galls/Burls  Sapwood damage/decay   
 Conks  Heartwood decay   
 Response growth       
 Condition(s) of concern       
 Part Size 100 mm dia. Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean      ° Corrected?       
 Response growth       
 Condition(s) of concern       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Roots and Root Collar —


Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity       % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk       
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size Whole tree Fall Distance 15 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

**Risk Categorization**

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>							
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>														
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe						
People in house	Branch Root plate	Failure			✓		✓					✓				✓								L	
				✓																					
House	Branch Root plate	Failure			✓		✓					✓				✓									L
				✓								✓			✓										
People using yard	Branch Root plate	Failure			✓		✓					✓													L
				✓									✓												


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---



---



---



---

**Mitigation options**

1. Periodic re-inspection Residual risk Low
2. \_\_\_\_\_ Residual risk \_\_\_\_\_
3. \_\_\_\_\_ Residual risk \_\_\_\_\_
4. \_\_\_\_\_ Residual risk \_\_\_\_\_

**Overall tree risk rating**      Low    Moderate    High    Extreme

**Overall residual risk**    None    Low    Moderate    High    Extreme     **Recommended inspection interval** 2 years

**Data** Final   Preliminary   **Advanced assessment needed** No   Yes-Type/Reason \_\_\_\_\_

**Inspection limitations**   None   Visibility   Access   Vines   Root collar buried   Describe Inspection undertaken from ground level only



# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 6/09/2022 Time 9:04:00 AM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3795095 -37.76965717 Tree no. 16 Sheet      of       
 Tree species Eucalyptus obliqua dbh 84 cm Height 30 m Crown spread dia. 10 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

## Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House		✓	✓	3	N	N
2	House			✓	✓	4	N	N
3	People using yard		✓	✓	✓	2	N	N
4								

## Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe       
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots  <10 % Describe Concrete slab in SRZ  
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

## Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

## Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

## Tree Defects and Conditions Affecting the Likelihood of Failure

### — Crown and Branches —

Unbalanced crown  LCR 50 %  
 Dead twigs/branches  5 % overall Max. dia. 150 mm  
 Broken/Hangers Number      Max. dia.       
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Branch failure      Condition(s) of concern       
 Part Size 150 mm dia. Fall Distance 30 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean 3 ° Corrected? No  
 Response growth       
 Condition(s) of concern       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Roots and Root Collar —

Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity       % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk in SRZ  
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size Whole tree Fall Distance 30 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### Risk Categorization

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>			
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>			Negligible	Minor	Significant	Severe				
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely						Very likely		
People in house	Branch Root plate	Failure			✓		✓						✓						✓		L
				✓						✓				✓						✓	
House	Branch Root plate	Failure			✓			✓					✓					✓			L
				✓						✓				✓						✓	
People using yard	Branch Root plate	Failure			✓			✓					✓						✓		L
				✓						✓				✓						✓	


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---

---

---

---

---

**Mitigation options**

- |                                    |                          |
|------------------------------------|--------------------------|
| 1. <u>Periodic re-inspection</u>   | Residual risk <u>Low</u> |
| 2. <u>Clean crown of dead wood</u> | Residual risk <u>Low</u> |
| 3. _____                           | Residual risk _____      |
| 4. _____                           | Residual risk _____      |

**Overall tree risk rating**      Low    Moderate    High    Extreme

**Overall residual risk**    None    Low    Moderate    High    Extreme       **Recommended inspection interval** 2 years

**Data**  Final    Preliminary   **Advanced assessment needed**  No    Yes-Type/Reason   Aerial inspection of crown to check for weak branch attachments

**Inspection limitations**  None    Visibility    Access    Vines    Root collar buried   Describe Inspection undertaken from ground level only





# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 6/09/2022 Time 9:15:00 AM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3794601, -37.76967431 Tree no. 17 Sheet      of       
 Tree species Eucalyptus goniocalyx dbh 70 cm Height 25 m Crown spread dia. 8 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

### Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3	N	N
2	House		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	4	N	N
3	People using yard		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	2	N	N
4								

### Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe       
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots  <10 % Describe Concrete slab in SRZ  
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

### Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

### Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

### Tree Defects and Conditions Affecting the Likelihood of Failure

#### — Crown and Branches —

Unbalanced crown  LCR 20 %  
 Dead twigs/branches  10 % overall Max. dia. 150 mm  
 Broken/Hangers Number      Max. dia.       
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Branch failure      Condition(s) of concern       
 Part Size 150 mm dia. Fall Distance 25 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent   
 Cracks  Lightning damage   
 Codominant  Included bark   
 Weak attachments  Cavity/Nest hole      % circ.  
 Previous branch failures  Similar branches present   
 Dead/Missing bark  Cankers/Galls/Burls  Sapwood damage/decay   
 Conks  Heartwood decay   
 Response growth     

#### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean 2 ° Corrected? No  
 Response growth       
 Condition(s) of concern       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

#### — Roots and Root Collar —

Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity       % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk in SRZ  
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size Whole tree Fall Distance 25 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent




### Risk Categorization

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>		
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>									
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe	
People in house	Branch Root plate	Failure			✓		✓					✓						✓		L
				✓					✓		✓								✓	L
House	Branch Root plate	Failure			✓					✓			✓				✓		L	
				✓					✓		✓					✓			L	
People using yard	Branch Root plate	Failure			✓		✓				✓							✓	L	
				✓			✓			✓								✓	L	


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---

---

---

---

---

**Mitigation options**

- |                                    |                          |
|------------------------------------|--------------------------|
| 1. <u>Periodic re-inspection</u>   | Residual risk <u>Low</u> |
| 2. <u>Clean crown of dead wood</u> | Residual risk <u>Low</u> |
| 3. _____                           | Residual risk _____      |
| 4. _____                           | Residual risk _____      |

**Overall tree risk rating**      Low     Moderate     High     Extreme

**Overall residual risk**    None     Low     Moderate     High     Extreme

**Recommended inspection interval** 2 years

**Data**  Final  Preliminary    **Advanced assessment needed**  No  Yes-Type/Reason    Aerial inspection of crown to check for weak branch attachments

**Inspection limitations**  None  Visibility  Access  Vines  Root collar buried    Describe Inspection undertaken from ground level only



# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 6/09/2022 Time 9:42:00 AM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3794097, -37.76969874 Tree no. 18 Sheet      of       
 Tree species Eucalyptus goniocalyx dbh 45 cm Height 15 m Crown spread dia. 7 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

## Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3	N	N
2	House		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	4	N	N
3	People using yard		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	2	N	N
4								

## Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe Stump holes dug in SRZ  
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots  % Describe       
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

## Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

## Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

## Tree Defects and Conditions Affecting the Likelihood of Failure

### — Crown and Branches —

Unbalanced crown  LCR 50 %  
 Dead twigs/branches  10 % overall Max. dia. 100 mm  
 Broken/Hangers Number      Max. dia.       
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Branch failure      Condition(s) of concern       
 Part Size 200 mm dia. Fall Distance 15 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent   
 Cracks  Lightning damage   
 Codominant  Included bark   
 Weak attachments  Cavity/Nest hole      % circ.  
 Previous branch failures  Similar branches present   
 Dead/Missing bark  Cankers/Galls/Burls  Sapwood damage/decay   
 Conks  Heartwood decay   
 Response growth Some callous formation around sapwood damage

### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean 10 ° Corrected? No  
 Response growth       
 Condition(s) of concern       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Roots and Root Collar —


Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity       % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk in SRZ  
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size Whole tree Fall Distance 15 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

**Risk Categorization**

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>							
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant	
People in house	Branch Root plate	Failure		✓				✓		✓					✓			M
				✓				✓		✓							✓	
House	Branch Root plate	Failure		✓				✓			✓			✓				M
				✓				✓			✓				✓			H
People using yard	Branch Root plate	Failure		✓			✓		✓							✓		L
				✓			✓		✓							✓		L


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---



---



---



---

**Mitigation options**

1. Periodic re-inspection Residual risk High
2. Tree removal Residual risk None
3. \_\_\_\_\_ Residual risk \_\_\_\_\_
4. \_\_\_\_\_ Residual risk \_\_\_\_\_

**Overall tree risk rating**      Low     Moderate     High     Extreme

**Overall residual risk**    None     Low     Moderate     High     Extreme       **Recommended inspection interval** 2 years

**Data** Final    Preliminary    **Advanced assessment needed** No    Yes-Type/Reason \_\_\_\_\_

**Inspection limitations**    None    Visibility    Access    Vines    Root collar buried    Describe Inspection undertaken from ground level only



# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 6/09/2022 Time 9:49:00 AM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.379404, -37.76970191 Tree no. 19 Sheet      of       
 Tree species Eucalyptus obliqua dbh 77 cm Height 30 m Crown spread dia. 13 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

## Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3	N	N
2	House			<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	4	N	N
3	People using yard		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	2	N	N
4								

## Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe Stump holes dug in SRZ  
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots  % Describe       
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

## Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

## Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

## Tree Defects and Conditions Affecting the Likelihood of Failure

### — Crown and Branches —

Unbalanced crown  LCR 30 % Cracks  Lightning damage   
 Dead twigs/branches  15 % overall Max. dia. 150 mm Codominant  Included bark   
 Broken/Hangers Number      Max. dia.      Weak attachments  Cavity/Nest hole      % circ.  
 Over-extended branches  Previous branch failures  Similar branches present   
**Pruning history**  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other      Conks  Heartwood decay   
 Response growth       
     Condition(s) of concern       
 Part Size 150 mm dia. Fall Distance 30 m Part Size      Fall Distance       
**Load on defect** N/A  Minor  Moderate  Significant  **Load on defect** N/A  Minor  Moderate  Significant   
**Likelihood of failure** Improbable  Possible  Probable  Imminent  **Likelihood of failure** Improbable  Possible  Probable  Imminent

### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean 3 ° Corrected? No  
 Response growth       
 Condition(s) of concern       
 Part Size      Fall Distance       
**Load on defect** N/A  Minor  Moderate  Significant   
**Likelihood of failure** Improbable  Possible  Probable  Imminent

### — Roots and Root Collar —


Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity  % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk in SRZ  
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size Whole tree Fall Distance 30 m  
**Load on defect** N/A  Minor  Moderate  Significant   
**Likelihood of failure** Improbable  Possible  Probable  Imminent

**Risk Categorization**

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>				
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>			Negligible	Minor	Significant	Severe					
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely						Very likely			
People in house	Branch Root plate	Failure			✓			✓					✓					✓				L
				✓						✓				✓							✓	
House	Branch Root plate	Failure			✓				✓					✓				✓				L
				✓						✓				✓						✓		
People using yard	Branch Root plate	Failure			✓			✓					✓							✓		L
				✓					✓					✓							✓	


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---



---



---



---

**Mitigation options**

1. Periodic re-inspection Residual risk Low
2. Clean crown of dead wood Residual risk Low
3. \_\_\_\_\_ Residual risk \_\_\_\_\_
4. \_\_\_\_\_ Residual risk \_\_\_\_\_

**Overall tree risk rating**      Low     Moderate     High     Extreme

**Overall residual risk**    None     Low     Moderate     High     Extreme       **Recommended inspection interval** \_\_\_\_\_

**Data**  Final     Preliminary    **Advanced assessment needed**  No     Yes-Type/Reason    Aerial inspection of crown to check for weak branch attachments

**Inspection limitations**  None     Visibility     Access     Vines     Root collar buried    Describe Inspection undertaken from ground level only



# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 6/09/2022 Time 9:54:00 AM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3793985, -37.76970577 Tree no. 20 Sheet      of       
 Tree species Eucalyptus obliqua dbh 37 cm Height 15 m Crown spread dia. 10 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

## Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3	N	N
2	House			<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	4	N	N
3	People using yard		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	2	N	N
4								

## Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe Stump holes dug in TPZ  
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots  % Describe       
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

## Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

## Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

## Tree Defects and Conditions Affecting the Likelihood of Failure

### — Crown and Branches —

Unbalanced crown  LCR 30 % Cracks  Lightning damage   
 Dead twigs/branches  15 % overall Max. dia. 100 mm Codominant  Included bark   
 Broken/Hangers Number      Max. dia.      Weak attachments  Cavity/Nest hole      % circ.  
 Over-extended branches  Previous branch failures  Similar branches present   
**Pruning history**  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other      Conks  Heartwood decay   
 Response growth       
     Condition(s) of concern       
 Part Size 100 mm dia. Fall Distance 15 m Part Size      Fall Distance       
**Load on defect** N/A  Minor  Moderate  Significant  **Load on defect** N/A  Minor  Moderate  Significant   
**Likelihood of failure** Improbable  Possible  Probable  Imminent  **Likelihood of failure** Improbable  Possible  Probable  Imminent

### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean      ° Corrected?       
 Response growth       
 Condition(s) of concern       
 Part Size      Fall Distance       
**Load on defect** N/A  Minor  Moderate  Significant   
**Likelihood of failure** Improbable  Possible  Probable  Imminent

### — Roots and Root Collar —


Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity       % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk in TPZ  
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size Whole tree Fall Distance 15 m  
**Load on defect** N/A  Minor  Moderate  Significant   
**Likelihood of failure** Improbable  Possible  Probable  Imminent

**Risk Categorization**

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>					
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>												
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe				
People in house	Branch Root plate	Failure		✓				✓					✓				✓					L	
				✓							✓										✓		
House	Branch Root plate	Failure		✓				✓					✓				✓					L	
				✓							✓									✓			L
People using yard	Branch Root plate	Failure		✓				✓					✓									✓	L
				✓							✓												✓


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---



---



---



---

**Mitigation options**

1. Periodic re-inspection Residual risk Low
2. \_\_\_\_\_ Residual risk \_\_\_\_\_
3. \_\_\_\_\_ Residual risk \_\_\_\_\_
4. \_\_\_\_\_ Residual risk \_\_\_\_\_

**Overall tree risk rating**      Low     Moderate     High     Extreme

**Overall residual risk**    None     Low     Moderate     High     Extreme       **Recommended inspection interval** 2 years

**Data** Final    Preliminary    **Advanced assessment needed** No    Yes-Type/Reason \_\_\_\_\_

**Inspection limitations**    None    Visibility    Access    Vines    Root collar buried    Describe Inspection undertaken from ground level only





# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 6/09/2022 Time 10:01:00 AM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.37936, -37.76969555 Tree no. 21 Sheet      of       
 Tree species Eucalyptus obliqua dbh 45 cm Height 20 m Crown spread dia. 6 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

## Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3	N	N
2	House	Other trees		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	4	N	N
3	People using yard	Other trees	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	2	N	N
4								

## Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe       
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots  % Describe       
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

## Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

## Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

## Tree Defects and Conditions Affecting the Likelihood of Failure

### — Crown and Branches —

Unbalanced crown  LCR 50 %  
 Dead twigs/branches  5 % overall Max. dia. 100 mm  
 Broken/Hangers Number      Max. dia.       
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Branch failure      Condition(s) of concern       
 Part Size 100 mm dia. Fall Distance 20 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean 5 ° Corrected? No - phototropic lean  
 Response growth       
 Condition(s) of concern       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Roots and Root Collar —

Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity       % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk       
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size Whole tree Fall Distance 20 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent




**Risk Categorization**

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>					
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>			Negligible	Minor	Significant	Severe						
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely						Very likely				
People in house	Branch Root plate	Failure		✓			✓						✓				✓					L	
				✓										✓								✓	L
House	Branch Root plate	Failure		✓			✓						✓				✓					L	
				✓										✓								✓	L
People using yard	Branch Root plate	Failure		✓			✓						✓									✓	L
				✓										✓									✓


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---



---



---



---

**Mitigation options**

1. Periodic re-inspection Residual risk L
2. \_\_\_\_\_ Residual risk \_\_\_\_\_
3. \_\_\_\_\_ Residual risk \_\_\_\_\_
4. \_\_\_\_\_ Residual risk \_\_\_\_\_

**Overall tree risk rating**      Low    Moderate    High    Extreme

**Overall residual risk**      None    Low    Moderate    High    Extreme       **Recommended inspection interval** 2 years

**Data** Final   Preliminary   **Advanced assessment needed** No   Yes-Type/Reason \_\_\_\_\_

**Inspection limitations**   None   Visibility   Access   Vines   Root collar buried   Describe Inspection undertaken from ground level only



# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 6/09/2022 Time 10:08:00 AM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3793413, -37.76972934 Tree no. 22 Sheet      of       
 Tree species Eucalyptus obliqua dbh 60 cm Height 30 m Crown spread dia. 8 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

## Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3	N	N
2	House	Other trees		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	4	N	N
3	People using yard		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	2	N	N
4								

## Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe       
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots       % Describe       
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

## Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

## Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

## Tree Defects and Conditions Affecting the Likelihood of Failure

### — Crown and Branches —

Unbalanced crown  LCR 25 %  
 Dead twigs/branches  20 % overall Max. dia. 150 mm  
 Broken/Hangers Number      Max. dia.       
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Branch failure      Condition(s) of concern       
 Part Size 150 mm dia. Fall Distance 30 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent   
 Cracks  Lightning damage   
 Codominant  Included bark   
 Weak attachments  Cavity/Nest hole      % circ.  
 Previous branch failures  Similar branches present   
 Dead/Missing bark  Cankers/Galls/Burls  Sapwood damage/decay   
 Conks  Heartwood decay   
 Response growth     

### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean      ° Corrected?       
 Response growth       
 Condition(s) of concern       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Roots and Root Collar —


Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity       % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk       
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size Whole tree Fall Distance 30 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### Risk Categorization

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>			
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>			Negligible	Minor	Significant	Severe				
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely						Very likely		
People in house	Branch Root plate	Failure			✓		✓						✓				✓				L
				✓					✓				✓							✓	L
House	Branch Root plate	Failure			✓		✓						✓				✓				L
				✓					✓				✓						✓		L
People using yard	Branch Root plate	Failure			✓		✓						✓							✓	L
				✓			✓						✓							✓	L


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---

---

---

---

---

**Mitigation options**

1. Periodic re-inspection Residual risk Low
2. Clean crown of dead wood Residual risk Low
3. \_\_\_\_\_ Residual risk \_\_\_\_\_
4. \_\_\_\_\_ Residual risk \_\_\_\_\_

**Overall tree risk rating**      Low    Moderate    High    Extreme

**Overall residual risk**    None    Low    Moderate    High    Extreme       **Recommended inspection interval** \_\_\_\_\_

**Data**  Final    Preliminary   **Advanced assessment needed**  No    Yes-Type/Reason   Aerial inspection of crown to check for weak branch attachments

**Inspection limitations**  None    Visibility    Access    Vines    Root collar buried   Describe Inspection undertaken from ground level only



# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 6/09/2022 Time 10:23:00 AM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3793791, -37.76962274 Tree no. 23 Sheet      of       
 Tree species Eucalyptus goniocalyx dbh 45 cm Height 18 m Crown spread dia. 8 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

## Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House		✓	✓	3	N	N
2	House	Other trees		✓	✓	4	N	N
3	People using yard		✓	✓	✓	2	N	N
4								

## Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe       
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots  % Describe       
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

## Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

## Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

## Tree Defects and Conditions Affecting the Likelihood of Failure

### — Crown and Branches —

Unbalanced crown  LCR 70 %  
 Dead twigs/branches  5 % overall Max. dia. 50 mm  
 Broken/Hangers Number      Max. dia.       
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Cracks  Lightning damage   
 Codominant  Included bark   
 Weak attachments  Cavity/Nest hole      % circ.  
 Previous branch failures  Similar branches present   
 Dead/Missing bark  Cankers/Galls/Burls  Sapwood damage/decay   
 Conks  Heartwood decay   
 Response growth       
 Condition(s) of concern       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean      ° Corrected?       
 Response growth       
 Condition(s) of concern       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Roots and Root Collar —


Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity       % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk       
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size Whole tree Fall Distance 18 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### Risk Categorization

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>								
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>			Negligible	Minor	Significant	Severe									
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely						Very likely							
People in house	Root plate	Failure																								
			✓					✓						✓											✓	
House	Root plate	Failure																								
			✓					✓						✓											✓	
People using yard	Root plate	Failure																								
			✓					✓						✓											✓	


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---

---

---

---

---

**Mitigation options**

1. Periodic re-inspection Residual risk Low

2. \_\_\_\_\_ Residual risk \_\_\_\_\_

3. \_\_\_\_\_ Residual risk \_\_\_\_\_

4. \_\_\_\_\_ Residual risk \_\_\_\_\_

**Overall tree risk rating**      Low     Moderate     High     Extreme

**Overall residual risk**    None     Low     Moderate     High     Extreme       **Recommended inspection interval** 2 years

**Data** Final    Preliminary    **Advanced assessment needed** No    Yes-Type/Reason \_\_\_\_\_

**Inspection limitations**    None    Visibility    Access    Vines    Root collar buried    Describe Inspection undertaken from ground level only



# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 6/09/2022 Time 10:29:00 AM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3793197, -37.76959833 Tree no. 24 Sheet      of       
 Tree species Eucalyptus obliqua dbh 38 cm Height 25 m Crown spread dia. 6 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

## Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	3	N	N
2	House	Other trees		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	4	N	N
3	People using yard		<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	2	N	N
4								

## Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe       
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots       % Describe       
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

## Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

## Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

## Tree Defects and Conditions Affecting the Likelihood of Failure

### — Crown and Branches —

Unbalanced crown  LCR 40 %  
 Dead twigs/branches  5 % overall Max. dia. 50 mm  
 Broken/Hangers Number      Max. dia.       
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Cracks  Lightning damage   
 Codominant  Included bark   
 Weak attachments  Cavity/Nest hole      % circ.  
 Previous branch failures  Similar branches present   
 Dead/Missing bark  Cankers/Galls/Burls  Sapwood damage/decay   
 Conks  Heartwood decay   
 Response growth       
 Condition(s) of concern       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean      ° Corrected?       
 Response growth       
 Condition(s) of concern       
 Part Size      Fall Distance       
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

### — Roots and Root Collar —


Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity       % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk       
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size Whole tree Fall Distance 25 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

**Risk Categorization**

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>			
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>			Negligible	Minor	Significant	Severe				
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely						Very likely		
People in house	Root plate	Failure		✓				✓					✓						✓	L	
House	Root plate	Failure		✓					✓				✓						✓	L	
People using yard	Root plate	Failure		✓					✓				✓						✓	L	


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---



---



---



---

**Mitigation options**

1. Periodic re-inspection Residual risk Low
2. \_\_\_\_\_ Residual risk \_\_\_\_\_
3. \_\_\_\_\_ Residual risk \_\_\_\_\_
4. \_\_\_\_\_ Residual risk \_\_\_\_\_

**Overall tree risk rating**      Low     Moderate     High     Extreme

**Overall residual risk**    None     Low     Moderate     High     Extreme       **Recommended inspection interval** 2 years

**Data**  Final     Preliminary    **Advanced assessment needed**  No     Yes-Type/Reason \_\_\_\_\_

**Inspection limitations**     None     Visibility     Access     Vines     Root collar buried    Describe Inspection undertaken from ground level only





# Basic Tree Risk Assessment Form

Client Yarra Ranges Council Date 6/09/2022 Time 10:44:00 AM  
 Address/Tree location 134 Hereford Rd, Mount Evelyn VIC 3796 / 145.3795485, -37.76948652 Tree no. 25 Sheet      of       
 Tree species Eucalyptus radiata dbh 90 cm Height 30 m Crown spread dia. 20 m  
 Assessor(s) Nicholas Magree Tools used DBH tape, soil probe Time frame 2 years

### Target Assessment

Target number	Target description	Target protection	Target zone			Occupancy rate 1 – rare 2 – occasional 3 – frequent 4 – constant	Practical to move target?	Restriction practical?
			Target within drip line	Target within 1 x Ht.	Target within 1.5 x Ht.			
1	People in house	House		✓	✓	3	N	N
2	House	Other trees		✓	✓	4	N	N
3	Cars	Other trees		✓	✓	3	N	N
4	People using yard		✓	✓	✓	2	N	N

### Site Factors

History of failures Yes Topography Flat  Slope  10 % Aspect South  
 Site changes None  Grade change  Site clearing  Changed soil hydrology  Root cuts  Describe       
 Soil conditions Limited volume  Saturated  Shallow  Compacted  Pavement over roots  % Describe       
 Prevailing wind direction SW Common weather Strong winds  Ice  Snow  Heavy rain  Describe     

### Tree Health and Species Profile

Vigor Low  Normal  High  Foliage None (seasonal)  None (dead)  Normal 90 % Chlorotic      % Necrotic      %  
 Pests/Biotic      Abiotic       
 Species failure profile Branches  Trunk  Roots  Describe     

### Load Factors

Wind exposure Protected  Partial  Full  Wind funneling  Relative crown size Small  Medium  Large   
 Crown density Sparse  Normal  Dense  Interior branches Few  Normal  Dense  Vines/Mistletoe/Moss   
 Recent or expected change in load factors     

### Tree Defects and Conditions Affecting the Likelihood of Failure

#### — Crown and Branches —

Unbalanced crown  LCR 40 %  
 Dead twigs/branches  <5 % overall Max. dia. 250 mm  
 Broken/Hangers Number      Max. dia.       
 Over-extended branches   
 Pruning history  
 Crown cleaned  Thinned  Raised   
 Reduced  Topped  Lion-tailed   
 Flush cuts  Other       
 Branch failure      Condition(s) of concern       
 Part Size 250 mm dia. Fall Distance 20 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

#### — Trunk —

Dead/Missing bark  Abnormal bark texture/color   
 Codominant stems  Included bark  Cracks   
 Sapwood damage/decay  Cankers/Galls/Burls  Sap ooze   
 Lightning damage  Heartwood decay  Conks/Mushrooms   
 Cavity/Nest hole      % circ. Depth      Poor taper   
 Lean      ° Corrected?       
 Response growth Yes, response growth at stem union  
 Condition(s) of concern Stem union failure  
 Part Size 500 mm dia. Fall Distance 30 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent

#### — Roots and Root Collar —

Collar buried/Not visible  Depth      Stem girdling   
 Dead  Decay  Conks/Mushrooms   
 Ooze  Cavity       % circ.  
 Cracks  Cut/Damaged roots  Distance from trunk       
 Root plate lifting  Soil weakness   
 Response growth       
 Condition(s) of concern Root plate failure  
 Part Size Whole tree Fall Distance 30 m  
 Load on defect N/A  Minor  Moderate  Significant   
 Likelihood of failure Improbable  Possible  Probable  Imminent




### Risk Categorization

Target <i>(Target number or description)</i>	Tree part	Condition(s) of concern	Likelihood											Consequences				Risk rating <i>(from Matrix 2)</i>		
			Failure				Impact				Failure & Impact <i>(from Matrix 1)</i>									
			Improbable	Possible	Probable	Imminent	Very low	Low	Medium	High	Unlikely	Somewhat	Likely	Very likely	Negligible	Minor	Significant		Severe	
People in house	Branch	Failure			✓		✓					✓					✓			L
	Stem union			✓				✓				✓							✓	L
	Root plate		✓					✓				✓								✓
House	Branch	Failure			✓		✓					✓					✓			L
	Stem union			✓					✓			✓						✓		L
	Root plate		✓						✓			✓							✓	L
Cars	Branch	Failure			✓		✓					✓					✓			L
	Stem union			✓					✓			✓						✓		L
	Root plate		✓					✓				✓						✓		L
People using yard	Branch	Failure			✓		✓					✓							✓	L
	Stem union			✓				✓				✓							✓	L
	Root plate		✓					✓				✓							✓	L


Matrix 1. Likelihood matrix.

Likelihood of Failure	Likelihood of Impact			
	Very low	Low	Medium	High
Imminent	Unlikely	Somewhat likely	Likely	Very likely
Probable	Unlikely	Unlikely	Somewhat likely	Likely
Possible	Unlikely	Unlikely	Unlikely	Somewhat likely
Improbable	Unlikely	Unlikely	Unlikely	Unlikely



Matrix 2. Risk rating matrix.

Likelihood of Failure & Impact	Consequences of Failure			
	Negligible	Minor	Significant	Severe
Very likely	Low	Moderate	High	Extreme
Likely	Low	Moderate	High	High
Somewhat likely	Low	Low	Moderate	Moderate
Unlikely	Low	Low	Low	Low



**Notes, explanations, descriptions**

---

---

---

---

---

**Mitigation options**

1. Periodic re-inspection Residual risk Low
2. Clean crown of dead wood Residual risk Low
3. \_\_\_\_\_ Residual risk \_\_\_\_\_
4. \_\_\_\_\_ Residual risk \_\_\_\_\_

**Overall tree risk rating**      Low     Moderate     High     Extreme

**Overall residual risk**    None     Low     Moderate     High     Extreme       **Recommended inspection interval** 2 years

**Data**  Final     Preliminary    **Advanced assessment needed**  No     Yes-Type/Reason    Undertake tomography of the decayed stem above the stem union

**Inspection limitations**  None     Visibility     Access     Vines     Root collar buried    Describe Inspection undertaken from ground level only